


Стул ХАУС OS-2049K-1

ASSEMBLING INSTRUCTION


1 X1PC




2 X1PC



3 X4PCS



A X12PCS




M6*16


B X8PCS




C X1PC



1



3



1

