



Инструкция по сборке

**Матисс 2.0 КЗ Л
гостиная 2Я1Д
2130x440x1910**





35-40 min

x1




x1





x1





x1



10MM



- | | |
|---------|---------|
| 1 - x2 | 12 - x5 |
| 2 - x2 | 22 - x1 |
| 3 - x2 | 23 - x1 |
| 4 - x2 | 30 - x1 |
| 5 - x2 | 32 - x8 |
| 6 - x2 | 47 - x1 |
| 7 - x2 | 49 - x1 |
| 9 - x2 | 51 - x3 |
| 10 - x4 | 70 - x2 |
| 11 - x4 | 71 - x2 |
| | 75 - x1 |



A - x20




B - x20




C - x20



D - x58




E - x46



F - x2



G - x2



H - x7




I - x2



J - x44



K - x110



L - x1



M - x4



N - x4



O - x12






P - x8






Q - x4




R - x4






7

8x




8

5x




9


10x




10




11






12




13







17




18





19





20





Регулировка петель



± 7.0 мм



± 2.5 мм



± 2.0 мм

